



## Rain Bird® Two-Wire PAR+ES Controllers

Two-Wire PAR+ES Controllers install quickly, boast the best-in-class user interface pedestal enclosure and are durably constructed. The base configuration of 16 stations can be upgraded at any time — in eight-station increments up to 72 stations — to accommodate changing course irrigation requirements. In the central control mode, an unlimited number of irrigation schedules can be programmed to further enhance watering flexibility and precision. To safeguard the controller investment, a choice of pedestals in either green or grey are available to provide superior environmental protection.


In this section are the recommended Rain Bird troubleshooting procedures for these performance challenges:

- Controller Does Not Power Up Properly
- Front Panel Does Not Power Up Properly
- Tripping Circuit Breaker
- Stations Not Working
- Key Pad Not Responding
- Controller Not Responding To MAXI® Signal





## Component Flow Chart



## Tools Required


- Flat head screwdriver
- Philips screwdriver
- Digital multi-meter
- Clip-on fuse holder and set of alligator clips

## Error Codes

- **Error. Incompatible OSM:** ROM-8 being used or damaged OSM
- **ROM Memory Error:** EPROM is defective
- **RAM Memory Error:** Dallas Chip is defective
- **Breaker Tripped:** Circuit breaker is open
- **RT Clock Error:** Dallas Chip is defective
- **No Boards Found:** No OSM installed or first OSM is damaged
- **Hardware Failure:** PIB is defective or main power not clean

## Terminology and Acronyms

- Control Module Assembly = Front Panel = Faceplate
- Erasable Programmable Read-only Memory: **EPROM**
- Light Emitting Diode: **LED**
- Liquid Crystal Display: **LCD**
- Main Logic Board: **MLB**
- Maxi Interface Module: **MIM**
- Output Station Module: **OSM**
- Power Interconnect Board: **PIB**
- Random Access Memory: **RAM**, e.g. Dallas Chip
- Relay Output Module: **ROM-8**
- Two-wire Interface Module: **IFB**






## Two-Wire PAR+ES Controllers




### POWER INTERCONNECT BOARD (PIB)




» Note: PAR+/PAR+ES and MSC+ PIB's are not interchangeable. Installing the wrong boards will result in a "Hardware Failure" error code.

### OUTPUT STATION MODULE (OSM)




» Note: OSMs replaced Relay Output Modules (ROM-8) in 2002. Installing ROM-8s in a controller manufactured after 2002 will result in an "Incompatible OSM" error code.

### TWO-WIRE INTERFACE MODULE (IFB)




### MAIN LOGIC BOARD (MLB)





Recommended Rain Bird®  
 Troubleshooting Procedure for  
 "Front Panel Does Not  
 Power Up Properly"






## Two-Wire PAR+ES Controllers




### POWER INTERCONNECT BOARD (PIB)




» Note: PAR+/PAR+ES and MSC+ PIB's are not interchangeable. Installing the wrong boards will result in a "Hardware Failure" error code.

### OUTPUT STATION MODULE (OSM)




» Note: OSMs replaced Relay Output Modules (ROM-8) in 2002. Installing ROM-8s in a controller manufactured after 2002 will result in an "Incompatible OSM" error code.

### TWO-WIRE INTERFACE MODULE (IFB)




### MAIN LOGIC BOARD (MLB)





“Tripping Circuit Breaker”






## Two-Wire PAR+ES Controllers




### POWER INTERCONNECT BOARD (PIB)




» Note: PAR+/PAR+ES and MSC+ PIB's are not interchangeable. Installing the wrong boards will result in a "Hardware Failure" error code.

### OUTPUT STATION MODULE (OSM)




» Note: OSMs replaced Relay Output Modules (ROM-8) in 2002. Installing ROM-8s in a controller manufactured after 2002 will result in an "Incompatible OSM" error code.

### TWO-WIRE INTERFACE MODULE (IFB)



### MAIN LOGIC BOARD (MLB)








# “All/Some Stations Not Working”

Front panel indicates that stations  
are running but no irrigation

» Note: This  
troubleshooting card  
assumes that water  
and pressure are ok.






## Two-Wire PAR+ES Controllers




### POWER INTERCONNECT BOARD (PIB)




» Note: PAR+/PAR+ES and MSC+ PIB's are not interchangeable. Installing the wrong boards will result in a "Hardware Failure" error code.

### OUTPUT STATION MODULE (OSM)





» Note: OSMs replaced Relay Output Modules (ROM-8) in 2002. Installing ROM-8s in a controller manufactured after 2002 will result in an "Incompatible OSM" error code.

### TWO-WIRE INTERFACE MODULE (IFB)



### MAIN LOGIC BOARD (MLB)





## How to perform a Factory Reset/Cold Boot with a non-responding key pad

1. Turn Power **OFF**
2. Hold **COPY PASTE** and **SYSTEM INFORMATION**
3. Turn Power **ON**
4. Hold button down until **NEW SYSTEM SETUP** appears in display






## Two-Wire PAR+ES Controllers




### POWER INTERCONNECT BOARD (PIB)




» Note: PAR+/PAR+ES and MSC+ PIB's are not interchangeable. Installing the wrong boards will result in a "Hardware Failure" error code.

### OUTPUT STATION MODULE (OSM)




» Note: OSMs replaced Relay Output Modules (ROM-8) in 2002. Installing ROM-8s in a controller manufactured after 2002 will result in an "Incompatible OSM" error code.

### TWO-WIRE INTERFACE MODULE (IFB)



### MAIN LOGIC BOARD (MLB)






# “Controller Not Responding to MAXI® Signal”

» Note 1: This troubleshooting section assumes that the MAXI Interface Module is functioning properly and not the cause of the problem.

» Note 2: In a two-wire system, Control Mode LED should turn solid within one minute.






## Two-Wire PAR+ES Controllers




### POWER INTERCONNECT BOARD (PIB)




» Note: PAR+/PAR+ES and MSC+ PIB's are not interchangeable. Installing the wrong boards will result in a "Hardware Failure" error code.

### OUTPUT STATION MODULE (OSM)




» Note: OSMs replaced Relay Output Modules (ROM-8) in 2002. Installing ROM-8s in a controller manufactured after 2002 will result in an "Incompatible OSM" error code.

### TWO-WIRE INTERFACE MODULE (IFB)



### MAIN LOGIC BOARD (MLB)





## Testing of MSP-1 Surge Arrestor

### When installed properly:

- All three wires are a continuous path through the LINE and EQUIP ends
- The green wire from both ends must be physically grounded together
- The MSP-1 surge arrester unit is directional and the end marked LINE must be connected to the two-wire path coming from the field.

### Test procedure:

Use digital multi-meter on its Ohm setting

- Check for continuity through red to red, black to black, and green to green. Reading should be  $\sim 0\Omega$ .
- There should NOT be continuity between any wire of mixed colors. Reading should be  $\sim 750\Omega$ .

The failure of any of the above tests indicates a malfunctioning surge arrester and will not provide any further protection and necessitates the replacement of the current MSP-1

